







Assemble Instruction




HARDWARE LIST

A	 M6x100mm	04
B	 M6x70mm	08
C	 M6	12
D	 Φ6x100mm	06
E	 Ø8x30mm	30
F	 Ø4x30mm	32


G		08
H	 Φ4mm	01
I	 Φ7x60mm	04
J		04
K	 Ø3.5x16mm	08






PARTS LIST




Step 1








A	 M6x100mm	04
C	 M6	04
D	 $\Phi 6 \times 100 \text{mm}$	06

Step 3




B	 M6x70mm	08
C	 M6	08
I	 $\Phi 7 \times 60 \text{mm}$	04

Step 4




F



Ø4x30mm

24


Step 5





G




06



G			02
F		 Ø4x30mm	08

Step 7



K		 Ø3.5x16mm	08
---	---	---	----

