




NO	PART NAME	PCS	A		B		C		ASSEMBLY INSTRUCTION	
			 SCREW	 LEG	 WINGNUT					
1	HEADBOARD	1								
2	BEDBASE	1	4 PCS	6 PCS	4 PCS					